



Anchor Environmental, L.L.C.
6650 SW Redwood Lane, Suite 110
Portland, OR 97224
Phone 503.670.1108
Fax 503.670.1128

Fax Transmission

To: Rod Struck

From: John Renda

Fax Number: (503) 229-6899

Date: June 24, 2002

Re: Brix Historical Drainage Pattern Review Total No. of Pages Including Cover: 4

Comments:

Rod -

We reviewed the 1961 aerial photo, traced and overlaid 1961 site features on the 1998 aerial photo. We could not get an exact match due to the slight variation in the angle of the photo. Note that the drainage pattern in 1961 does not represent natural topography, but rather post fill conditions. Please refer to 1936 aerial photo that shows a small shoreline embayment. The embayment is filled by the time of the 1961 photo. Using the 1998 photo with the 1961 drainage pattern overlay, it appears that the proposed site of monitoring well MW-4 should be in a good location to address this potential migration pathway.

I have the 1961 and 1998 aerial photographs with overlays in Corel Draw format. I could send these electronically, but they are huge (10-12 meg each). I also have the aerial photos in JPEG format without the overlays (0.5 to 1 meg each).

Let us know if you have any questions.

This facsimile is confidential and may also be attorney-privileged. If you are not the intended recipient or the person responsible for its distribution, please call us collect immediately at 503.670.1108 and return the original to us via the U.S. Postal Service. Thank you.

cc:

USEPA SF



1187227

1936





